

Procedure for mounting the chassis



Expansion screw



Strickle

Cement screw

Scraper screw



Ceiling plate

Colloidal particles

1. insert the expansion screw into the cement
2. fix the cement screw and scraper to the ceiling
3. loosen the rubber particles to adjust the length of the wire length of the wire and then tighten the rubber tighten the rubber particles.
4. after fixing the scraper, connect the cable and mount the screws of the wiper